

RUDDER TUBE - 3/8" WALL
2.9"+ I.D.

TUBE IS GLASSED TO UNDERSIDE OF BEARING HOUSING - GLASSED WITH 3 STAGGERED LAYERS OF PROMAT

NOTES

1. RUDDER POST CAP IS FASTENED WITH A 3/8" BOLT.

2. RUDDER POST CAP IS 3/8 THICK - 1 1/2 OZ MAT & 7 1/2 OZ CLOTH LAMINATE.

CATALINA YACHTS 21200 VICTORY BLVD. ~~WOODLAND HILLS, CA~~		
SCALE: NONE	APPROVED BY:	DRAWN BY GB
DATE: 7-26-94		REVISED
UPPER RUDDER BEARING SCHEMATIC		
CATALINA 34, 36		DRAWING NUMBER 340-